



# Product Safety Recall

## Metzeler Tourance Next



## Metzeler Tourance Next II



**IDENTIFICATION:** All tyres with Tyre ID and Date Code combination listed below.

Brand	Model Name	Tyre ID on sidewall	Production Date Code on sidewall
Metzeler	Metzeler 150/70R18 M/C TL 70V Tourance Next	(1)EB 0M X033	From 4816 to 2424
Metzeler	Metzeler 150/70R18 M/C TL 70V Tourance Next II	(1)EB 0M 614L	From 3521 to 2624



**Why the product is recalled:** Under certain tyre service conditions (e.g., low inflation pressure, heavy load, road conditions, mileage at almost the half of tyre life, etc.), irregular tyre wear may develop, which, over time, may result in breakage of the zero-degree reinforcement. If this condition is not promptly detected, it may lead to potential detachment of parts of the tread layer and/or sudden air loss.

**Hazard:** Partial detachment of the tread layer and/or a sudden loss of air pressure may cause loss of control, increasing the risk of a crash.



1. Metzeler recommends to stop using the motorbike immediately and have the tyre checked by your Metzeler Dealer.
2. Pirelli will support your dealer in replacing the affected tyres you return.



For more information, please contact your Metzeler Dealer where you purchased your product from or contact Pirelli Tyres Australia Pty Ltd on +61 1300 300 008 or [contactcentretyres@pirelli.com.au](mailto:contactcentretyres@pirelli.com.au).



**Purchased from:** Pirelli Tyres Australia sold the product through the following distributor : **Cassons Pty Ltd**

See [productsafety.gov.au](http://productsafety.gov.au) for  
Australian product recall information